SECRET



OUT62337

1837 JUN 19 22 25 Z

DISTRIBUTION

Eile OS

CY NO.

Office

Action

P 192157Z JUN 67
FM NPIC WASHDC
TO RUCSAAA/SAC OFFUTT AFB OMAHA NEB
RUCVAAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
RUCVAAA/2D RTS BARKSDALE AFB LA
RUEPJS/DIA WASHDC
RUCIJRA/NAVRECONTECHSUPPCEN SUITLAND MD
RUEPIA/CIA WASHDC
RUWBKNA/15TH AF MARCH AFB RIVERSIDE CALIF
RUCVAAA/2 AF BARKSDALE AFB LA
BT
S E C R E T CITE NPIC 0999.

15TH AF (FOR DI), SAC (FOR DIM/GLASS LAMP/DOCR, DM 4)
2D AF (FOR DI).

- CAMERA B-24 WAS USED ON MISSION G 963 FLOWN ON 15
   JUNE 1967. PROCESSING WAS ACCOMPLISHED BY NAV TECH RECON SUPPCEN.
  - 2. ORIGINAL NEGATIVE:
- A. DENSITY IS GOOD BUT RESOLUTION IS POOR BECAUSE OF A POSSIBLE VACUUM LOSS.
- B. 9R SIDE: STATIC IS PRESENT ON THE OUTBOARD EDGE THROUGH OUT THE MISSION. HEAT SPLICES ARE PRESENT BETWEEN FRAMES 691/692 AND IN FRAME 639. THE POSITION INDICATORS MALFUNCTIONED (FAILED TO APPEAR) AFTER FRAME 1185.
- C. 9L SIDE: STATIC IS PRESENT ON OUTBOARD EDGE THROUGH SEC BR TDS

  FRAME 900. THERE IS A HEAT SPLICE IN FRAME 582 AND A MANU
  FACTURERS SPLICE IN FRAME 849. ALL POSITION INDICATORS MAL
  FUNCTIONED (FAILED TO APPEAR) AFTER FRAME 1200 EXCEPT THE 1L34 540

  INDICATOR. ALSO FILM METERING IS SLIGHTLY ERRATIC AFTER FRAME

  1185.
- D. BOTH SIDES: THE LAST TITLED FRAME IS A PARTIAL FRAME NUMBERED 1304. IMAGERY IS DEGRADED THROUGHOUT BECAUSE OF THE POSSIBLE VACUUM LOSS.
  - 3. POSITIVE:
    - A. PRINTING AND PROCESSING ARE GOOD.
    - B. PI SUITABILITY IS POOR.
    - C. CLOUDS OBSCURE APPROXIMATELY 80 PERCENT OF THE MISSION.

**GP-1** 

SECRET

SECRET ----END OF MESSAGE----

CROUP 1
Excluded from automatic designation and deciassification